

VEHICLE INSPECTION REPORT

CU14CCY

Ford Transit 125 2.2 TDCI 125PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/07/2014

Year 2014

Mileage 106,238 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTFXDD14592

Body Style Panel Van LWB

CAP Clean £1,975.00

CAP Average £1,625.00

CAP Below £1,125.00

Gearbox MANUAL

Gears 6

COLLECTED AS NON RUNNER, TURBO FAILURE SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Other
N/A
N/A



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Other
N/A
N/A



7: Other
N/A
N/A



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



10: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



11: Other
N/A
N/A



12: Door Moulding osf
Broken
Replace



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Seat Base Cover osf
Holed
Over 3mm



16: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		