

VEHICLE INSPECTION REPORT

CV66FYC

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 14/10/2016

Year 2016

Mileage 62,166 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXGA14204

Body Style Panel Van L2

MOT Due Expired

CAP Clean £4,375.00

CAP Average £3,650.00

CAP Below £2,700.00

Gearbox MANUAL

Gears 6

COLLECTED AS NON RUNNER, ENGINE FAILURE SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
Over 30mm



4: Front TowEye Cvr
Missing
Replace



5: Wing nsf
Scratched
UpTo 25mm Not Thru Paint



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Flasher Side Repeater ns
Broken
Replace



8: Door nsr
Chipped
Over 5mm



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
Over 30mm



11: Other
N/A
N/A



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



14: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



15: Qtr Panel nsr
Dented
Over 30mm



16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



20: Door osf
Scratched
UpTo 25mm Not Thru Paint



21: Other
N/A
N/A

22: Other
N/A
N/A



23: Other
N/A
N/A

24: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	Fault
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK