

VEHICLE INSPECTION REPORT

CV66PCO

Ford Transit 350 2.2 TDCI 150PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	18/10/2016	VIN	WF0XXXTTGXGA14212	CAP Below	£2,075.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	113,955 Miles Warranted	MOT Due	28/10/2025	Gears	6
Fuel Type	Diesel	CAP Clean	£3,375.00		
Colour	WHITE	CAP Average	£2,825.00		

NON RUNNER, POWERS UP DOES NOT CRANK, PARTIALLY STRIPPED SHELVES IN REAR, TOW BAR, SIDE LOADING DOOR, PLASTIC LINED

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Front TowEye Cvr
Missing
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Panel Front
Scratched
UpTo 25mm Thru Paint



8: Handle Outer nsr
Broken
Replace



9: Door nsr
Hole
Over 10mm



10: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Other
N/A
N/A



12: Door nsr
Dented
Between 10mm + 30mm




13: Other
N/A
N/A



14: Door nsr
Dented
Between 10mm + 30mm



15: Door Moulding nsr
Scuffed (Unpainted)
UpTo 100mm



16: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



17: Qtr Panel Arch Extension ns
Broken
Replace



18: Qtr Panel Trim ns
Scuffed
Over 25mm



19: Door osr
Dented
Between 10mm + 30mm



20: Seat Base Cover osf
Holed
Over 3mm



21: Other
N/A
N/A



22: Other
N/A
N/A



23: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Engine Runs Fault