

VEHICLE INSPECTION REPORT

PN18DKF

FIAT DUCATO II 42 2.3 MULTIJET

| Inspection | Vehicle |
|------------|---------|
| | |

| VAT | Plus VAT | | |
|-----|----------------|--|--|
| V5 | Buyer To Apply | | |

Details

| Reg. date | 23/05/2018 | Fuel Type | Diesel | Body Style | Ambulance |
|-----------|----------------------------|-----------|-------------------|------------|------------|
| Year | 2018 | Colour | YELLOW | MOT Due | 08/01/2026 |
| Mileage | 142,661 Miles Warranted | VIN | ZFA25000002G40400 | Gearbox | MANUAL |

SIDE LOAD DOOR, RAMP AT REAR

| 1 | v | r | Δ | c |
|---|---|---|---|---|
| • | y | • | · | • |

NSF

NSR OSF

OSR

Spare

Features

Air conditioning

• Front electric windows

• Leather seat trim

Photos



















