

# VEHICLE INSPECTION REPORT

**SP60WCN**

## Ford Transit 300 2.2 TDCI 85ps

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	25/01/2011	Body Style	Panel Van MWB	CAP Below	£680.00
Year	2011	Keys	1	Gearbox	MANUAL
Mileage	77,175 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Diesel	MOT Due	30/01/2026	Doors	4
Colour	WHITE	CAP Clean	£1,275.00	Rear Suspension	Steel
VIN	WF0XXXTTFXAL61668	CAP Average	£1,000.00	Rear Doors	Barn

### Tyres

NSF

NSR

OSF

OSR


Spare

## Features

- Front electric windows
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Rusted  
UpTo 5mm



2: Wing of  
Dented  
Over 30mm



3: Door osf  
Dented  
Over 30mm



4: Qtr Panel osr  
Dented  
With Paint Damage



5: Tailgate  
Dented  
With Paint Damage



6: Qtr Panel nsr  
Rusted  
Over 5mm



7: Door nsr  
Dented  
Over 30mm



8: B Post ns  
Rusted  
Over 5mm



9: Door nsf  
Rusted  
Over 5mm

10: Wing nsf  
Rusted  
UpTo 5mm

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK