

VEHICLE INSPECTION REPORT

FN70BJX

Daf CF 340

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 13/10/2020

Year 2020

Mileage 416,003 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRASM4100G305997

Body Style Box Van

MOT Due 30/11/2025

Axle Combi 6x2

Rear Suspension Air

Tail Lift Cantilever

REAR LIFT AXLE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wings
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel Trim ns
Scuffed
Over 25mm



6: Qtr Panel Trim os
Scuffed
Over 25mm



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		