

VEHICLE INSPECTION REPORT

C388476

KRONE CURTAINSIDE EUROLINER

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2015	Colour	GREEN	Axle Combi	Tri
Year	2015	VIN	WKESD000000646814	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

BPW AXLES, RAISE AND LOWER VALVE, FERRY LASHING RINGS, ENXL RATED BODY & CURTAINS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



