

VEHICLE INSPECTION REPORT

SP11UXO

Ford Transit 350 2.2 TDCi 115ps FWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	31/03/2011	Body Style	Crew Van LWB	Gearbox	MANUAL
Year	2011	Service history	Yes	Gears	6
Mileage	90,815 Miles Warranted	MOT Due	Expired	Axle Combi	4x2
Fuel Type	Diesel	CAP Clean	£1,500.00	Steering Combi	Steer
Colour	WHITE	CAP Average	£1,175.00	Rear Suspension	Steel
VIN	WF0XXXTTFXAT13603	CAP Below	£800.00	Rear Doors	Barn

Power Steering Issues

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Sill os
Hole
UpTo 10mm



2: Bonnet
Rusted
Over 5mm



3: Bonnet
Rusted
Over 5mm



4: Door osf
Rusted
Over 5mm



5: B Post os
Rusted
Over 5mm



6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Dented
Over 30mm



8: Qtr Panel nsr
Rusted
Over 5mm



9: Sill ns
Rusted
Over 5mm



10: Door nsf
Rusted
Over 5mm



11: Wing nsf
Rusted
Over 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Clutch Slip Test from Static	OK	
Brakes	OK		No Excessive Smoking	OK	
Turbo Boosting	OK				
Parking Brake	OK				
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	

Windows	OK	Radio	OK
		Steering	OK