

VEHICLE INSPECTION REPORT

VN16PJU

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 20/06/2016

Year 2016

Mileage 125,299 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN SEG2628HR6BG22443

Body Style Refuse Collector

MOT Due 30/11/2025

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

OLYMPUS BODY, TERBERG SPLIT LIFT

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Grill
Broken
Replace



2: Panel Front
Scratched
Over 25mm Not Thru Paint



3: Wing of
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		