

VEHICLE INSPECTION REPORT

SP11UXU

Ford Transit 350 2.2TDCi 115PS FWD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	30/03/2011	Body Style	Crew Van LWB	Gearbox	MANUAL
Year	2011	Service history	Yes	Gears	6
Mileage	98,427 Miles Warranted	MOT Due	Expired	Axle Combi	4x2
Fuel Type	Diesel	CAP Clean	£1,425.00	Steering Combi	Steer
Colour	WHITE	CAP Average	£1,100.00	Rear Suspension	Steel
VIN	WF0XXXTTFXAT17500	CAP Below	£2,995.00	Rear Doors	Barn

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Sill os
Rusted
Over 5mm



3: Bonnet
Chipped
Multiple Chips



4: Wing osf
Hole
Over 10mm



5: Door osf
Rusted
Over 5mm



6: B Post os
Rusted
Over 5mm



7: Qtr Panel osr
Rusted
Over 5mm



8: Tailgate
Dented
With Paint Damage



9: Qtr Panel nsr
Rusted
Over 5mm



10: Door nsr
Dented
Over 30mm



11: B Post ns
Rusted
Over 5mm



12: Door nsf
Rusted
Over 5mm



13: Wing nsf
Rusted
Over 5mm



14: Roof
Rusted
Over 5mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK