

VEHICLE INSPECTION REPORT

VN16PJY


Dennis Elite 6

Inspection

Serious Damage? No


Vehicle

VAT Plus VAT





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips





3: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			