



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

VN16PKD

Dennis Elite 6

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	27/06/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	SEG2628HR6BG22449	Axle Combi	6x2
Mileage	128,808 Km Not Warranted	Body Style	Refuse Collector	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	CREW CAB		

OLYMPUS BODY, TERBERG SPLIT, SURROUND CAMERA SYSTEM



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Radio/CD
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

OK
Poor

Upholstery Condition
Odour

OK
-

Engine Runs

OK

No Excessive Smoking

OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK