

VEHICLE INSPECTION REPORT

VN16PKE

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	27/06/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	SEG2628HR6BG22450	Axle Combi	6x2
Mileage	127,318 Km Warranted	Body Style	Refuse Collector	Steering Combi	Rear Steer
Fuel Type	Diesel	Cab Type	CREW CAB	Rear Suspension	Air

OLYMPUS BODY, TERBERG SPLIT LIFT

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Cloth seat trim
- Digital radio
- Radio/CD


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Wing nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated

OK

DPF light illuminated

OK

ABS light illuminated

OK