

VEHICLE INSPECTION REPORT

VN16PKK

Dennis Elite 6

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/07/2016

Year 2016

Mileage 124,440 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN SEG2628HR6BG22455

Body Style Refuse Collector

MOT Due Expired

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear Steer

Rear Suspension Air

OLYMPUS BODY, TERBERG SPLIT LIFT

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Cloth seat trim
- Digital radio
- Radio/CD


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		