

VEHICLE INSPECTION REPORT

BX62NEN

Daf LF 45.210

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/12/2012

Year 2012

Mileage 102,417 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAE45FF0L420802

Body Style Vacuum Tanker

MOT Due Expired

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

WHALE 2,300L BODY, AD BLUE

Tyres

NSF NSI1 NSI2 NSI3 NSI4


OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4


Photos







Condition Check



Damage Photos



1: Bumper Front
Rusted
Over 5mm



2: Bonnet
Chipped
Multiple Chips




3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Other
N/A
N/A



5: Other
N/A
N/A



6: Bumper Rear
Rusted
Over 5mm



7: Other
N/A
N/A



8: Other
N/A
N/A



9: Door osf
Chipped
Edge Chip



10: Other
N/A
N/A



11: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	