

VEHICLE INSPECTION REPORT

BX59DFC

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	01/12/2009	VIN	XLRAE45FF0L354095	Cab Type	DAY CAB
Year	2009	Body Style	MOBILE WORKSHOP	Gearbox	MANUAL
Mileage	195,394 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Steel
Colour	WHITE	MOT Due	31/10/2025	Rear Doors	Roller

TWIN SIDE ROLLER SHUTTER DOORS, KITCHENETTE C/W SINK & HOB

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Digital radio
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Rusted
Over 5mm




3: Panel Front
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
Multiple Chips



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Qtr Panel Trim os
Scuffed
Over 25mm



9: Door Pad osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			