

VEHICLE INSPECTION REPORT

GK62OZB

MERCEDES-BENZ ACTROS

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	19/12/2012	VIN	WDB9634032L710284	Gearbox	AUTOMATIC
Year	2012	Body Style	Tractor Unit	Axle Combi	4x2
Mileage	916,337 Km Not Warranted	Service history	Yes	Rear Suspension	Air
Fuel Type	Diesel	Service documents	Printout		
Colour	WHITE	Cab Type	STREAMSPACE CAB (2.3M, FLAT FLOOR)		

*KEY BROKEN IN DRIVERS DOOR BARREL, WARNING LIGHTS ON DASH, MOT MILEAGE HISTORY POSSIBLE IN KM/MILES INCORRECTLY * TWIN FUEL TANKS, POWER INVERTER IN CAB

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Digital radio
- Air conditioning

Photos





