

VEHICLE INSPECTION REPORT

FN17BOU

DAF LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/07/2017

Year 2017

Mileage 375,103 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L462434

Body Style Curtainside

Service history Yes

Service documents Electronic / Online

MOT Due 31/07/2026

Cab Type DAY CAB

Axle Combi 4x2

Rear Suspension Air

Rear Doors Barn

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2



OSO3

OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front Moulding
Broken
Replace



3: Door osf
Dented
Over 30mm



4: Qtr Panel osr
Dented
Over 30mm



5: Tailgate
Rusted
Over 5mm



6: Door Moulding nsf
Broken
Replace

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK