

VEHICLE INSPECTION REPORT

GN13CDF

ISUZU FORWARD N75.190

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	25/04/2013	Colour	WHITE	Gearbox	AUTOMATIC
Year	2013	VIN	JAANPR75MD7100072	Axle Combi	4x2
Mileage	193,415 Km Not Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column

OUTSTANDING RECALL

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



