

VEHICLE INSPECTION REPORT

FN17BPK

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/06/2017

Year 2017

Mileage 461,683 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRAEL3700L462541

Body Style Curtainside

Service history Yes

Service documents Electronic / Online

MOT Due 30/06/2026

Cab Type DAY CAB

Gearbox AUTOMATIC

Rear Suspension Air

Rear Doors Barn

FORK LIFT BRACKETS, SURROUND CAMERA SYSTEM

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3




OSO4

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Park assist camera
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Bumper Front Moulding
Broken
Replace



7: Wing nsf
Cracked
Replace



8: Qtr Panel nsr
Hole
Over 10mm



9: Door nsr
 Scratched
 Over 25mm Thru Paint



10: Door Pad osf
 Soiled
 Heavy



11: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		