

VEHICLE INSPECTION REPORT

PJ16YTB

DAF LF 150

Accident Damage

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/06/2016

Year 2016

Mileage 917,325 Miles
Warranted

Fuel Type Diesel

Colour RED

VIN XLRAEL1500L455005

Body Style Box Van

MOT Due 28/02/2026

Cab Type DAY CAB

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

COLLECTED AS NON-RUNNER, MECHANICAL FIRE, INSURANCE TOTAL LOSS – CATEGORY N

WARNING LIGHTS ON DASH

Tyres

NSF NSI1 NSI2 NSI3 NSI4



OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



5: Other
N/A
N/A



6: Other
N/A
N/A



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Other
N/A
N/A



9: Door nsf
Chipped
Edge Chip



10: Other
N/A
N/A



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK