

VEHICLE INSPECTION REPORT

KU18DYT

MERCEDES-BENZ ANTOS 2545

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	02/05/2018	VIN	WDB96302020212320	Rear Suspension	Air
Year	2018	Body Style	Fridge Box	Rear Doors	Barn
Mileage	491,826 Km Warranted	Cab Type	DAY CAB	Tail Lift	Column
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	6x2		

FRIGOBLOCK UNIT, STANDBY PLUG, TWIN EVAP, SEPARATOR, REAR LIFT, SURROUND CAMERA SYSTEM, GARDNER DENVER HYDRAPAK

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Air conditioning

Photos





