

VEHICLE INSPECTION REPORT

C627997

BMI WALKING FLOOR

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2020	Colour	RED	Axle Combi	Tri
Year	2020	VIN	SA9WAS130LG176103	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Disc		

SHEET DAMAGED FRONT LIFT SAF AXLES, SHEETING SYSTEM, RAISE AND LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





