

VEHICLE INSPECTION REPORT

FH19WWN

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	14/06/2019	VIN	XLRAEL3700L484060	Axle Combi	4x2
Year	2019	Body Style	Curtainside	Rear Suspension	Steel
Mileage	442,102 Km Warranted	MOT Due	31/07/2026	Rear Doors	Barn
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		

EXHAUST BLOWING, WARNING LIGHT ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Central locking
- Park assist camera
- Cloth seat trim
- Digital radio
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Number Plate Front
Missing
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Unclassified
Major Parts Missing
Report Only



7: Door Pad osf
Soiled
Heavy



8: Seat Base Cover osf
Holed
Over 3mm



9: Seat Base Cover nsf
Soiled
Heavy



10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		Fault
ABS light illuminated		OK			