

VEHICLE INSPECTION REPORT

PE65VDG

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	29/10/2015	VIN	XLRAEL1500L448517	Axle Combi	4x2
Year	2015	Body Style	Box Van	Rear Suspension	Steel
Mileage	792,007 Km Warranted	MOT Due	30/09/2026	Tail Lift	Cantilever
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	RED	Gearbox	MANUAL		





COLLECTED AS NON-RUNNER, AD-BLUE PUMP & TANK REQUIRE ATT *WARNING LIGHTS ON DASH*
AD-BLUE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Scratched
Over 25mm Not Thru Paint



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Bonnet
Cracked
Replace



5: Door Mirror Assy nsf
Missing
Replace



6: Other
N/A
N/A



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Bumper Rear
Rusted
Over 5mm



11: Door Mirror Assy osf
Broken
Replace



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK