

VEHICLE INSPECTION REPORT

SA15BAG

Mercedes-Benz Arocs 3240

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	15/07/2016	VIN	WDB9642302L969247	CAP Below	£9,675.00
Year	2016	Body Style	Tipper	Cab Type	DAY CAB
Mileage	526,232 Km Warranted	MOT Due	31/03/2026	Gearbox	AUTOMATIC
Fuel Type	Diesel	CAP Clean	£13,350.00	Axle Combi	8x4
Colour	WHITE	CAP Average	£12,450.00	Rear Suspension	Steel

WARNING LIGHT ON DASH KELBERG BODY, HYVA TIPPING GEAR, AD-BLUE, SHEETING SYSTEM, WEIGH SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Fog Lamp Surrounds
Scuffed (Unpainted)
UpTo 100mm



2: Other
N/A
N/A



3: Other
N/A
N/A



4: Other
N/A
N/A



5: Other
N/A
N/A



6: Bumper Rear
Rusted
Over 5mm



7: Other
N/A
N/A



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Other
N/A
N/A



10: Other
N/A
N/A



11: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average	Average	Average	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault