

VEHICLE INSPECTION REPORT

BL68OVG

IVECO EUROCARGO 180-250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	19/02/2019	VIN	ZCFA71TJ902688734	Cab Type	DAY CAB
Year	2019	Body Style	Curtainside	Gearbox	AUTOMATIC
Mileage	287,159 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Steel
Colour	WHITE	MOT Due	28/02/2026	Rear Doors	Barn

WARNING LIGHT ON DASH WEIGH SYSTEM, SURROUND CAMERA SYSTEM, FORKLIFT BRACKET


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Front TowEye Cvr
Missing
Replace



4: Bumper Front Moulding
Broken
Replace



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Broken
Replace



7: Door Mirror Assy nsf
Missing
Replace



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		Fault		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	