

VEHICLE INSPECTION REPORT

PN71BVL

Fiat Doblo II 1.6 MULTIJET 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/11/2021

Year 2021

Mileage 97,584 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V34782

Body Style Pick-up

MOT Due 04/09/2026

CAP Clean £5,875.00

CAP Average £5,375.00

CAP Below £4,475.00

Gearbox MANUAL

Gears 5

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
With Paint Damage



3: Door Mirror Assy nsf
Broken
Replace



4: Lamp osr
Broken
Replace




5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Dented
With Paint Damage



7: B Post os
Dented
With Paint Damage



8: Seat Back Cover osf
Torn
Over 3mm



9: Seat Base Cover nsf
Soiled
Heavy

10: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		