

VEHICLE INSPECTION REPORT

C313873

DON BUR CURTAINSIDE DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2011	VIN	SEPBV38FXBL057977	Brakes	Disc
Year	2011	Body Style	Trailer	Axle Combi	Tri
Mileage	Not Showing	Service history	Yes	Rear Suspension	Air
Fuel Type		Service documents	Printout	Rear Doors	Roller
Colour	RED	MOT Due	28/02/2026		

CAT S REAR AND AND UNDERSIDE, CORROSION BPW AXLES, RAISE AND LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





