

VEHICLE INSPECTION REPORT

KX67PYJ

VOLVO FH 500

Axle Combi Steering Combi	6x2
· 	
· 	
· 	
Steering Combi	
	Mid-Lift
Rear Suspension	Air

Features

Digital radio

• Air conditioning

· Leather seat trim

Photos









