

VEHICLE INSPECTION REPORT

MJ16SXG

Peugeot Partner 850 1.6 HDI PROFESSIONAL

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/05/2016

Year 2016

Mileage 98,273 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF37D9HF0GJ647748

Body Style Panel Van L1

MOT Due 04/02/2026

CAP Clean £1,875.00

CAP Average £1,575.00

CAP Below £1,175.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag

Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsr
Chipped
Multiple Chips



4: Qtr Panel osr
Chipped
Multiple Chips



5: Seat Base Cover osf
Soiled
Heavy



6: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		