

VEHICLE INSPECTION REPORT

MK67XNP

Ford Ranger XL 2.2 TDCI 150PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/01/2018

Year 2018

Mileage 160,444 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN 6FPPXXMJ2PHR81671

Body Style Pickup Double Cab

MOT Due Expired

Gearbox MANUAL

Gears 6

Axle Combi 4x4

OUTSTANDING RECALL AD-BLUE, TOW BAR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm




3: Wing nsf
Dented
With Paint Damage



4: Sill ns
Dented
With Paint Damage



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Fascia Panel
Missing
Replace



7: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		No	
Engine Runs		OK	No Excessive Smoking
			OK
EML light illuminated		OK	DPF light illuminated
			OK
ABS light illuminated		OK	