

VEHICLE INSPECTION REPORT

FP74TKF

Ford Transit 2.0 136PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	31/12/2024	VIN	WF0RXXTA4RPU68394	CAP Below	£20,400.00
Year	2024	Body Style	Panel Van	Gearbox	MANUAL
Mileage	12,075 Miles Not Warranted	MOT Due	30/12/2027	Gears	6
Fuel Type	Diesel	CAP Clean	£23,600.00	Doors	5
Colour	SILVER	CAP Average	£22,700.00		

WARNING LIGHT ON DASH APPLE CAR PLAY, SIDE LOAD DOOR, E/MIRRORS, HEATED WINDSCREEN, AD BLUE.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front parking sensor
- Radio/CD
- Heated front seat
- Air conditioning
- Park assist camera
- Front electric windows
- Rear parking sensor
- Central locking

Photos





Condition Check



Damage Photos



1: Qtr Panel osr
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Dented
Over 30mm

4: Bumper Rear
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition

-

Upholstery Condition

-

Seat Condition

-

Odour

-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		