

VEHICLE INSPECTION REPORT

EA21FHH

Ford Transit Connect 210 1.5 ECO BLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 05/05/2021

Year 2021

Mileage 62,083 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSMM81398

Body Style Panel Van L2

MOT Due 10/12/2025

CAP Clean £6,475.00

CAP Average £5,875.00

CAP Below £4,950.00

Gearbox MANUAL

Gears 6

NO ACCESS TO REAR AD-BLUE, SIDE LOADING DOOR, SPARE WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Glass ns
Broken
Replace



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



8: Other
N/A
N/A



9: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK