

VEHICLE INSPECTION REPORT

EA21FHE

Ford Transit Custom 300 2.0 ECOBLUE 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/04/2021

Year 2021

Mileage 52,928 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYMU89556

Body Style Panel Van L2

MOT Due 03/12/2025

CAP Clean £9,375.00

CAP Average £8,525.00

CAP Below £7,175.00

Gearbox MANUAL

Gears 6

DEAD LOCKS WITH KEYS, AD-BLUE, SIDE LOADING DOOR, SPARE WHEEL, PLY LINED

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Panel Front
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
2 Or Less UpTo 10mm



7: Door nsr
Scratched
UpTo 25mm Not Thru Paint



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
Over 30mm



10: Door nsr
Dented
Over 30mm



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel osr
Dented
With Paint Damage



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK