

VEHICLE INSPECTION REPORT

EA21FGN

Ford Transit Custom 300 2.0 ECOBLUE 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/04/2021

Year 2021

Mileage 32,258 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYMU89557

Body Style Panel Van L2

MOT Due 07/02/2026

CAP Clean £10,950.00

CAP Average £9,975.00

CAP Below £8,350.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOADING DOOR, SPARE WHEEL, PLY LINED, DEADLOCKS WITH KEYS

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Front parking sensor
- Central locking
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Panel Front
Cracked
Replace



2: Fog Lamp Surround os
Broken
Replace




3: Bumper Front Moulding
Broken
Replace



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Door nsr
Scratched
UpTo 25mm Not Thru Paint



7: Door osf
Chipped
Edge Chip



8: Other
N/A
N/A



9: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK