

VEHICLE INSPECTION REPORT

EA21FGZ

Ford Transit Custom 300 2.0 ECOBLUE 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/04/2021

Year 2021

Mileage 70,602 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYMU89554

Body Style Panel Van L2

MOT Due 04/02/2026

CAP Clean £8,200.00

CAP Average £7,450.00

CAP Below £6,275.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOADING DOOR, SPARE WHEEL, PLY LINED, DEADLOCKS WITH KEY

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Panel Front
Scratched
Over 25mm Thru Paint



5: Other
N/A
N/A



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Sill ns
Dented
With Paint Damage



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Dented
Over 2 UpTo 10mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Door osr
Hole
Over 10mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Dented
With Paint Damage



16: Door osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK