

VEHICLE INSPECTION REPORT

EO21YCZ

Ford Transit Connect 230 1.5 ECO BLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 22/03/2021

Year 2021

Mileage 76,022 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF05XXWPG5LT33024

Body Style Crew Van L2

MOT Due 18/11/2025

CAP Clean £7,150.00

CAP Average £6,525.00

CAP Below £5,475.00

Gearbox MANUAL

Gears 6

AD-BLUE, TWIN LOADING DOORS, PARTLY PLY LINED

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Door nsf
Scratched
UpTo 25mm Not Thru Paint



5: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Door osr
Dented
With Paint Damage



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK