

VEHICLE INSPECTION REPORT

C391511

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date		Colour	GREEN	Axle Combi	Tandem
Year	2015	VIN	SEPBV33ABFL063656	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

BPW AXLES, RAISE AND LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



