

VEHICLE INSPECTION REPORT

NJ65OLX

RENAULT KANGOO ML19 1.5 DCI 75PS

Inspection

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/10/2015	VIN	VF1FW17BD53587524	CAP Below	£775.00
Year	2015	Body Style	Panel Van	Gearbox	MANUAL
Mileage	132,440 Miles Not Warranted	MOT Due	19/11/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£1,300.00		
Colour	WHITE	CAP Average	£1,050.00		

INPUT ERROR ON MOT SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Front electric windows
- Central locking

Photos



