

VEHICLE INSPECTION REPORT

BX65FEK

Renault T 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/09/2015

VIN VF611C169GD002007

Axle Combi 6x2

Year 2015

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 1,062,566 Km Not Warranted

MOT Due 30/11/2025

Rear Suspension Air

Fuel Type Diesel

Cab Type HIGH ROOF SLEEPER CAB

Colour WHITE

Gearbox AUTOMATIC

SLIDING 5TH WHEEL

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features


- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Digital radio
- Central locking
- Radio/CD
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Missing
Replace



3: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



4: Qtr Panel Trim ns
Scuffed
Over 25mm



5: Qtr Panel Trim ns
Broken
Replace



6: Qtr Panel Trim os
Broken
Replace



7: Door osf
Dented
With Paint Damage



8: Door osf
Dented
With Paint Damage



9: Screen Front
Chipped
Over 10mm

10: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		