

# VEHICLE INSPECTION REPORT

**SJ67KPN**

## MERCEDES-BENZ ACTROS

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                      |            |                                       |                 |          |
|-----------|----------------------|------------|---------------------------------------|-----------------|----------|
| Reg. date | 30/01/2018           | VIN        | WDB96342320151917                     | Axle Combi      | 6x2      |
| Year      | 2018                 | Body Style | Tractor Unit                          | Steering Combi  | Mid-Lift |
| Mileage   | 556,253 Km Warranted | MOT Due    | 30/04/2026                            | Rear Suspension | Air      |
| Fuel Type | Diesel               | Cab Type   | STREAMSPACE CAB<br>(2.5M, FLAT FLOOR) |                 |          |
| Colour    | BLACK                | Gearbox    | AUTOMATIC                             |                 |          |

\*WARNING LIGHT ON DASH\* SLIDING 5TH WHEEL

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Air conditioning

## Photos







