

VEHICLE INSPECTION REPORT

YD18BXU

Ford Transit Connect 240 1.5 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 27/04/2018

VIN WF0SXXWPGSJL70139

CAP Below £2,750.00

Year 2018

Body Style Panel Van L2

Gearbox MANUAL

Mileage 89,806 Miles
Warranted

MOT Due 26/04/2026

Gears 5

Fuel Type Diesel

CAP Clean £4,050.00

Colour WHITE

CAP Average £3,500.00

A/C, SIDE LOADING DOOR, E/WINDOWS, FRONT & REAR SENSORS

Tyres

NSF

NSR


OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Bumper Front Grill
Broken
Replace




2: Bumper Front
Insecure
Action Required



3: Screen Front
Chipped
UpTo 10mm



4: Screen Front
Chipped
UpTo 10mm



5: General Exterior
Soiled
Light



6: Bumper Rear
Insecure
Action Required



7: Bumper Rear
Insecure
Action Required

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK