

VEHICLE INSPECTION REPORT

SD64YJU

Volkswagen Transporter Shuttle T30 2.0 TDI 84PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/10/2014

Year 2014

Mileage 89,033 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV2ZZZ7HZFH041351

Body Style Minibus

MOT Due 21/06/2026

CAP Clean £9,450.00

CAP Average £7,650.00

CAP Below £5,350.00

Gearbox MANUAL

Gears 5

E/MIRRORS, TWIN SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door osf
Dented
Over 30mm



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: Tailgate
Dented
Over 30% Of Panel



5: Qtr Panel nsr
Dented
Over 30mm



6: Door nsr
Dented
Over 30% Of Panel



7: Door nsf
Dented
Over 30% Of Panel



8: Sill ns
Dented
Over 30mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK