

VEHICLE INSPECTION REPORT

EY66NDX

Man TGX 26.500

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	01/02/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	WMA24XZZ3HP084621	Axle Combi	6x2
Mileage	Not Showing	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	XXL CAB	Rear Suspension	Air

NON RUNNER - NO KEYS, NO ENGINE/GEARBOX OR CALLIPERS SLIDING 5TH WHEEL

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Leather seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Flasher Side Repeater ns
Missing
Replace



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Unclassified
Major Parts Missing
Report Only



7: Unclassified
Major Parts Missing
Report Only



8: Qtr Panel osr
Chipped
Multiple Chips



9: Door osf
Chipped
Multiple Chips



10: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition OK
Seat Condition Poor

Upholstery Condition OK
Odour -

Engine Runs Fault