

VEHICLE INSPECTION REPORT

C324061

CARTWRIGHT BOX DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2011	VIN	120075	Brakes	Disc
Year	2011	Body Style	Trailer	Axle Combi	Tri
Mileage	TBC	Service history	Yes	Rear Suspension	Air
Fuel Type		Service documents	Printout	Rear Doors	Roller
Colour	RED	MOT Due	01/01/2026		

FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



