

VEHICLE INSPECTION REPORT

BX09GSZ

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	10/08/2009	VIN	XLRAE45FF0L353418	Cab Type	DAY CAB
Year	2009	Body Style	MOBILE WORKSHOP	Gearbox	MANUAL
Mileage	261,496 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Steel
Colour	WHITE	MOT Due	31/01/2026	Rear Doors	Roller

AIR BRAKE AND SUSPENSION REQUIRE ATTENTION TWIN SIDE ROLLER SHUTTER DOOR, KITCHEN INC GAS HOB, SINK & SEATING

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
Over 30% Of Panel



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Cracked
Replace



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



8: Flasher Side Repeater ns
Broken
Replace



9: Door Pad osf
Soiled
Heavy



10: Seat Base Cover osf
Holed
Over 3mm



11: Seat Base Cover nsf
Soiled
Heavy



12: In Car Entertainment
Missing
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		