

VEHICLE INSPECTION REPORT

SJ70GMO

Renault T 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 24/09/2020

Year 2020

Mileage 509,044 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF611C362LD002101

Body Style Tractor Unit

Cab Type SLEEPER CAB

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHT ON DASH SLIDING 5TH WHEEL UNEVEN BRAKE PAD WEAR, MAINTANENCE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Bluetooth connection
- USB/iPod interface
- Drivers airbag
- Cruise control
- Electric sunroof
- Central locking
- Navigation system
- Air conditioning
- Cloth seat trim
- Mobile phone App interface
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint



2: Headlamp os
Broken
Replace



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Brakes	Fault		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault