

VEHICLE INSPECTION REPORT

MA56284

KRONE CURTAINSIDE MEGA EUROLINER

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2015	Colour	BLUE	Axle Combi	Tri
Year	2015	VIN	WKES000000682205	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

NOT REGISTERED IN THE UK, REAR DOOR DAMAGED BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, SLIDING ROOF, ENXL RAYED BODY

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





