

Inspection

VEHICLE INSPECTION REPORT

MA56223

KRONE CURTAINSIDE MEGA EUROLINER

Vehicle

		VAT V5	Plus VAT Present		
Details					
Reg. date	01/01/2015	Colour	BLUE	Axle Combi	Tri
Year	2015	VIN	WKESD000000	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		
*NOT REGIS	STERED IN THE UK	* BPW AXLES. RA	ISE & LOWER VALV	/E. FERRY LASHIN	G RINGS. ENXL
*NOT REGIS RATED Tyres NSF	STERED IN THE UK	* BPW AXLES, RA	ISE & LOWER VALV	/E, FERRY LASHIN	G RINGS, ENXL
RATED Tyres	STERED IN THE UK	* BPW AXLES, RA	ISE & LOWER VALV	/E, FERRY LASHIN	G RINGS, ENXL
RATED Tyres NSF	STERED IN THE UK	* BPW AXLES, RA	ISE & LOWER VALV	/E, FERRY LASHIN	G RINGS, ENXL
Tyres NSF NSR	STERED IN THE UK	* BPW AXLES, RA	ISE & LOWER VALV	E, FERRY LASHIN	G RINGS, ENXL